

BUILDING I

Unit	Age & Brand	Tonnage	Temp. Difference	Heat Pump or Straight cool & tonb	Pressures	Amp draw	Comments				
301	2024 Carrier	3 ton		SC	2.5 ton	110/231	6.2 Good Condition	Unable to get temp split 67 in home thermostat would not go that low			
302	2010 York	2.5 ton	66 in, 46 out	SC	2 ton	100/208	6.6 Fair Condition				
303	2021 York	3 ton	66 in, 58 out	HP	2 ton Mini	102	2.1 Fair Condition				
304	1995 Trane	2 ton	68 in, 47 out	SC	2 ton	49/132 R-22	6.7 Poor Condition	R-22 refrigerant strongly suggest replacing system			
305	2019 Carrier	2.5 ton	67 in, 47 out	SC	2 ton	103/220	4.8 Fair Condition				
306	2018 Daikin	3 ton	68 in, 46 out	SC	3 ton	98/195	7.9 Fair Condition				
307	2019 Carrier	2 ton	73 in, 53 out	SC	2 ton	105/206	4.6 Fair Condition				
308	2015 Rheem	3 ton	64 in, 49 out	SC	2.5 ton	108/221	6.4 Poor Condition				
208	2022 trane			SC	2 ton	101/215	5.1 Good Condition	couldnt get inside but condenser on roof was running			
207	2020 Carrier	2 ton	66 in, 47 out	SC	2 ton	108/201	4.2 Good Condition				
206	2024 Trane	2.5 ton	71 in, 51 out	SC	2 ton	121/231	5.5 Good Condition				
205	2021 Goodman	2.5 ton	68 in, 49 out	SC	2 ton	96/204	5.5 Fair Condition				
204	2019 Trane	2 ton	70 in, 49 out	SC	2 ton	105/214	5.4 Good Condition				
203	2018 Carrier	2 ton	69 in, 52 out	SC	2 ton	84/223	4.9 Fair Condition				
202	2012 Rheem	2 ton	71 in, 55 out	SC	2 ton	110/201	6.2 Poor Condition	Green dye in refrigerant indicating previous leak sealed with stop leak			
201	2017 Lennox	2.5 ton	72 in, 50 out	SC	2.5 ton	102/213	6.3 Good Condition				
101	2021 York	2.5 ton	69 in, 50 out	SC	2.5 ton	101/215	6.7 Good Condition				
102	2021 Trane	2 ton	72 in, 50 out	SC	2 ton	109/229	5.1 Good Condition				
103	2011 Rheem	2 ton	71 in, 56 out	SC	2 ton	94/211	6.3 Poor Condition				
104	2014 Trane	2 ton	74 in, 54 out	SC	2 ton	123/209	4.5 Poor/Fair				
105	2011 Rheem	3 ton	70 in, 49 out	SC	2.5 ton	107/256	7.6 Poor Condition				
106	2004 Trane	2.5 ton	76 in, 59 out	SC	2.5 ton	47/151 R-22	9.1 Poor Condition	R-22 refrigerant strongly suggest replacing system			
107	2021 Rheem	2 ton	72 in, 54 out	SC	2 ton	102/212	4.9 Good Condition				
108	2021 Carrier	2 ton	70 in, 51 out	SC	2 ton	114/225	5 Good Condition				