

BUILDING L

Unit	Age & Brand	Tonnage	Temp. Difference	Heat Pump or Straight cool & tonb	Pressures	Amp draw	Comments						
301	2011 Rheem	3 ton	72 in, 54 out	SC	2.5 ton	104/232	6.9	Poor Condition					
302	2019 Goodman			SC	2 ton			Fair Condition	Could not get into home				
303	2017 Daikin	3 ton		SC	3 ton	110/202	7.3	Fair Condition	60 degrees in home thermostat didnt go lower but ran fan to test condenser				
304	2022 Lennox	2 ton	60 in, 43 out	SC	2 ton	115/218	5.6	Good Condition	Condenser has bad contactor				
305	2011 Daikin	2.5 ton	69 in, 50 out	SC	2 ton	114/215	5.7	Fair/ Poor					
306	2020 ICP	3 ton	62 in, 42 out	SC	3 ton	97/232	8.2	Fair Condition	Condenser has bad contactor				
307	2013 Carrier	2.5 ton	74 in, 51 out	SC	2.5 ton Bryant	90/228	6.8	Poor Condition					
308	2023 Carrier	2.5 ton	74 in, 55 out	SC	2.5 ton	114/221	6.2	Good Condition					
208	1999 Lennox	2.5 ton		SC	2.5 ton			Poor Condition	No refrigerant in system				
207	2013 Rheem	2 ton	69 in, 52 out	SC	2 ton	97/147	6.2	Poor Condition					
206	2017 Carrier	2 ton	66 in, 47 out	SC	2 ton	107/215	5	Fair Condition					
205	2022 York	2 ton	65 in, 43 out	SC	2 ton	95/220	5.2	Good Condition	Noisy contactor				
204	2021 Rheem	2 ton	63 in, 47 out	SC	2 ton	108/230	5.6	Fair/Good					
203	2022 Carrier	2 ton	66 in, 46 out	SC	2 ton	107/217	5.2	Good Condition					
202	2015 Rheem	2 ton	71 in, 54 out	SC	2 ton	121/247	5.6	Poor Condition					
201	2020 Rheem	3 ton	65 in, 48 out	SC	2.5 ton	106/238	6.8	Good Condition					
101	2015 Daikin	2.5 ton	70 in, 54 out	SC	2 ton	116/232	5.9	Poor Condition					
102	2023 Rheem	2 ton	68 in, 50 out	SC	2 ton	107/218	4.9	Good Condition					
103	2017 Daikin	2.5 ton	74 in, 54 out	SC	2 ton	117/202	5.5	Fair Condition					
104	2018 Carrier	2 ton	66 in, 49 out	SC	2 ton	112/221	5.8	Good Condition					
105	2013 Trane	2 ton	68 in, 51 out	SC	2 ton	100/232	5.7	Poor Condition					
106	2005 Trane	2 ton	65 in, 50 out	SC	2 ton	51/168 R-22	7.7	Poor condition	R- 22 refrigerant strongly suggest changing the system				
107	2024 Rheem	2 ton	70 in, 54 out	SC	2 ton	115/227	5.4	Good Condition					
108	1989 Bryant	2 ton		SC	2 ton 1995	R-22		Poor condition	No refrigerant, R-22 system needs replaced.				