

BUILDING E

Unit	Age & Brand	Tonnage	Temp Difference	Heat pump or Straight cool & Ton	Pressures	Amp Draw	Comments				
301	2017 Trane	2.5 ton	75 in, 60 out	SC 2.5 ton	115/220	6.3	Good condition				
302	2022 Trane	2 ton	72 in, 50 out	SC 2 ton	113/232	5.6	Good condition				
303	2007 Carrier	2.5 ton	75 in, 57 out	SC 2 ton	105/219	4.4	Poor condition				
304	2016 Daikin	2 ton	74 in, 60 out	SC 1.5 ton	140/225	4.1	Poor condition				
305	2016 Goodman	2.5 ton	77 in, 58 out	SC 2 ton	104/217	5.7	Fair/poor				
306	2018 Trane	2.5 ton	73 in, 53 out	SC 2.5 ton	123/226	6.2	Fair condition				
307	2018 Carrier	2 ton	75 in, 63 out	SC 2 ton	72/200	5.9	Fair condition	Unit low on refrigerant not cooling well			
308	2021 Daikin	2.5 ton	75 in, 60 out	SC 2.5 ton	130/215	6.6	Fair condition				
208	2022 Daikin	2.5 ton	74 in, 50 out	SC 2.5 ton	110/217	6	Good condition				
207	2010 Lennox	2 ton	76 in, 58 out	SC 2 ton	134/243	6	Poor condition	fan motor noise			
206	2016 ICP	2 ton	75 in, 55 out	SC 2 ton	119/211	4.5	Fair/ poor				
205	2024 Trane	2 ton	78 in, 56 out	SC 2 ton	121/221	5.2	Good condition				
204	2014 Goodman	2 ton	74 in, 59 out	SC 2 ton	78/195	5.5	Poor condition	Unit low on refrigerant			
203	2023 Lennox	2 ton	76 in, 55 out	SC 2 ton	118/209	5	Good condition				
202	2022 ICP	2 ton	75 in, 55 out	SC 2 ton	123/217	4.8	Good condition				
201	2021 Goodman	2 ton	76 in, 57 out	SC 2 ton	128/228	5.8	Good condition				
101	2018 Carrier	2 ton	77 in, 58 out	SC 2 ton	103/234	5.5	Fair condition				
102	2018 Carrier	2 ton	78 in, 58 out	SC 2 ton	110/222	5.1	Fair condition				
103	2020 Daikin	2.5 ton	71 in, 51 out	SC 2 ton	114/239	5.5	Fair condition				
104	2015 Daikin	2 ton	77 in, 69 out	SC 2 ton	62/189	5.2	Poor condition	Unit very low on refrigerant not cooling well			
105	2017 ICP	2 ton	79 in, 58 out	SC 2 ton	122/246	5.7	Fair condition				
106	2013 ICP	1.5 ton	78 in, 58 out	SC 1.5 ton	125/230	4.3	Poor condition				
107	2018 Trane	2 ton	80 in, 60 out	SC 2.5 ton	117/223	6.7	Fair condition	disconnect was pulled from condenser unit, we put it in and unit ran			
108	2016 Daikin	3 ton	75 in, 55 out	SC 2.5 ton	126/260	7.5	Fair condition				